



Tree Survey Reference	British Standard Category	Identified for removal in Phase 1A South*
G061	B2	Large group of trees. Some trees feature minor defects such as stem asymmetry, crown, mild deadwood. Maximum DBH crown diameter given in schedule. Accurate DBH crown diameter on drawing. Limited TOPO data. Individual constituent trees poor but coalesce to create a notable landscape feature. 4 x Norway maple, 1 x Red oak, 1 x Lime, 1 x Ash and 1 x Sorbus to be removed from this group.
G098	C2	Large group of trees. All trees feature significant defects. Weak unions on scaffold limbs. Included bark. Trees with landscape value but significant defects.
G099	C2	Small group of trees. All trees feature minor defects. Weak unions on scaffold limbs. Bark wounds on base of stem. Bark wounds on main stem. Poor form. Individual constituent trees poor but coalesce to create a notable feature. 1 x Lime to be removed from this group.
T343	B2	Highways tree. No indicators of disease/decay/structural defects. Minor deadwood. Restricted root zone. A tree with slight impaired condition.

**BRENT CROSS PHASE 1A SOUTH**

**SCHOOL LANE TREE REMOVAL PLAN**

16 Benthams Yard  
London EC1V 4JL  
United Kingdom  
T +44 (0)207 812 8000  
F +44 (0)207 812 8399  
www.bdp.com

DATE: 22/10/15

PROJECT NO: P2007004

DATE: 22/10/15

SCALE: 1:300 @ A1

REVISION: (97)LP005

BUILDING DESIGN PARTNERSHIP SHALL HAVE NO RESPONSIBILITY FOR ANY USE OF THIS DOCUMENT OTHER THAN THAT FOR WHICH IT WAS PREPARED AND ALL DIMENSIONS SHOULD BE CHECKED ON SITE. DO NOT SCALE FOR CONSTRUCTION PURPOSES. DRAWING ERRORS OR OMISSIONS SHOULD BE BROUGHT TO THE ATTENTION OF BUILDING DESIGN PARTNERSHIP AT THE ADDRESS SHOWN BELOW.

**NOTES**

Plan to be read in conjunction with following documents:

- Tree survey, Arboricultural Impact Assessment, Arboricultural Method Statement and Tree Protection Plan in accordance with BS5837: 2012 prepared by Haydens Arboricultural Consultants
- Survey of Schedule 9 Listed Invasive Weed Species prepared by Ecolat Environmental

All tree works should adhere to current best practice detailed within BS 5827:2012 (Trees in relation to design, demolition and construction - recommendations) For removal of existing trees within tree protective fencing areas and/or within Root Protection Areas of other trees, refer to Haydens Arboricultural Consultants' document listed above

The position, condition and dimensions of the trees are based on a site survey undertaken on 12/02/14

The original of this drawing was produced in colour - a monochrome copy should not be relied upon

All existing trees to be removed as approved under Condition 27.1 for Phase 1(A/N) RMA are not shown on this plan. This plan only shows additional trees to be removed within 10 metres of the Phase 1(A/S) RMA boundary.

**LEGEND**

- Boundary of School Lane Reserved
- Matters Application
- Trees and Vegetation to be Related
- Trees and Vegetation to be Removed under Phase 1A South Application

0 10 50m

FRST ISSUE FOR INFORMATION YL MS 22/10/15